

Phenobarbital VET control kit



For veterinary use only!


For quality control procedures of the quantitative determination with the Phenobarbital VET test kit on a solo or CUBE-VET analyser



Eurolyser Diagnostica GmbH
Bindergasse 3
5020 Salzburg/Austria

Tel. +43 (0)662 / 43 21 00
Fax +43 (0)662 / 43 21 00-50
www.eurolyser.com

English

	Order information Order number: VT 0211 Order number: VT 2100	Indication Phenobarbital VET test kit Phenobarbital VET control kit	Kit size 6 tests/pack 1 x 5 ml (decision level)
---	--	--	--



Test kit preparation: Allow single test at least 10 minutes to warm up to room temperature (20 - 25 °C) by placing the test into the test kit rack. Put test kit package back into refrigerator.

Summary

This Phenobarbital VET control kit is a valuable tool for assuring quality and precision of the Phenobarbital VET test kit (VT0211) and provides a reliable marker for monitoring the accuracy of results.

Required Material

(not supplied with the kit)

- Pipettes

Preparation and Handling

The control is liquid and ready to use. Thoroughly mix the contents of the vial before each use by gently inverting for several minutes. Open the vial and transfer the required quantity of control into a clean sample cup. Use sample cup only for one measurement circle and use new sample cups further on to avoid contamination of the control liquid. Replace the cap immediately and store the opened vial at 2 – 8 °C. Always use disposable pipette tips!

Stability and Storage

Unopened vials are stable at 2 – 8 °C until the expiration date stated on the label. Once opened, vials of control are stable for 30 days when stored tightly capped at 2 – 8 °C. Bacterial contamination produces an increase in turbidity and/or a characteristic odor. Discard vial if evidence of microbial contamination is observed. DO NOT FREEZE!

Waste Management

Please refer to local legal requirements

Warnings and Precautions

This control kit is for veterinary diagnostic use only!
DO NOT INGEST! Exercise the normal precautions required for handling all laboratory reagents.



Set the species to „Control“ before running the QC material



Compare the results with the values indicated in the lot-specific value table



If the result is not within the acceptable range, repeat measurement. If result is again not within the acceptable range, please contact your distributor

Durchführung einer **Phenobarbital** VET Kontrollmessung Processing of a **Phenobarbital** VET control measurement

1.

CUBE-VET SOLO

1.1 → 1.2 → 1.3 → 1.4

CUBE-VET SOLO

1.4

2.

CUBE-VET SOLO

2.1 → 2.2

3.

3.1 → 3.2 → 3.3 → 3.4

CUBE-VET SOLO

3.4

Deutsch

ACHTUNG!


Einzeltest mindestens 10 Minuten vor Gebrauch bei Raumtemperatur (20 - 25 °C) aufwärmen lassen!

- 1. Testsystem vorbereiten**
 - 1.1 RFID-Karte platzieren
 - 1.2 ERS Küvette in Probenhalter geben
 - 1.3 ERS Kappe in Probenhalter geben
 - 1.4 „Messung“-Taste drücken, die erforderlichen Daten über den Touchscreen eingeben

- 2. Vorbereitung der Kontrolle**

Für weitere Details beachten Sie bitte das Anwenderhandbuch des Laborphotometers

 - 2.1 Als Spezies „Kontrolle“ auswählen
 - 2.2 20 µl Kontrollflüssigkeit aus Kontrollfläschchen mit Pipette aufsaugen

- 3. Abarbeitung der Kontrolle**
 - 3.1 20 µl Kontrollflüssigkeit IN DIE FLÜSSIGKEIT in der ERS Küvette abgeben
 - 3.2 ERS Kappe fest auf ERS Küvette setzen
 - 3.3 ERS Cartridge in Laborphotometer einsetzen.
 - 3.4 Automatische Abarbeitung der Kontrolle durch Drücken des  Start Buttons am solo Laborphotometer, bzw. durch Schließen der Türe am CUBE-VET Laborphotometer.

English

ATTENTION!


Allow single test at least 10 minutes to warm up to room temperature (20 - 25 °C) before use!

- 1. Preparation of test system**
 - 1.1 Place RFID card
 - 1.2 Place ERS cuvette in test kit rack
 - 1.3 Place ERS cap in test kit rack
 - 1.4 Press „Measurement“ button, enter required information using the touchscreen

- 2. Control preparation**

For further details please see user manual of laboratory photometer

 - 2.1 Set species to „Control“
 - 2.2 Aspirate 20 µl control liquid out of control vial using a pipette

- 3. Control processing**
 - 3.1 Dispense 20 µl control liquid INTO THE LIQUID in the ERS cuvette
 - 3.2 Apply ERS cap firmly onto ERS cuvette
 - 3.3 Place ERS cartridge into laboratory photometer
 - 3.4 Start automatic control processing by pressing the  start button on the solo laboratory photometer, or by closing the door of the CUBE-VET laboratory photometer.

Wertetabelle für das Phenobarbital VET control kit Value sheet for the Phenobarbital VET control kit

LOT

2406-2



2025-08

Kontrollwerte | Control Values


Target	value (min)	value (max)
27.80 µg/ml	16.68 µg/ml	38.92 µg/ml

Technical details subject to change without notice.

Doc-ID: 9f3a4f9b-8e6a-48f7-817e-fc342cd451cb ; latest revision: DP 5.0 ; date of print: 2020-07-30


Nur für den Veterinärgebrauch!

Für Verfahren zur Qualitätskontrolle der quantitativen Bestimmung mit dem Phenobarbital VET Testkit am solo oder CUBE-VET Analyser.

 Eurolyser Diagnostica GmbH
Bindergasse 3
5020 Salzburg/Austria

Tel. +43 (0)662 / 43 21 00
Fax +43 (0)662 / 43 21 00-50
www.eurolyser.com

Deutsch

	Bestellinformation	Bezeichnung	Packungsgröße
	Bestellnummer: VT 0211 Bestellnummer: VT 2100	Phenobarbital VET Testkit Phenobarbital VET Control Kit	6 Tests/Packung 1 x 5 ml (decision level)



Vorbereitung des Testkits: Der Einzeltest muss min. 10 Minuten auf Raumtemperatur (20 - 25 °C) aufgewärmt werden. Geben Sie dazu den Test aus der Packung und setzen Sie ihn in das Testkit-Rack. Geben Sie die Testpackung zurück in den Kühlschrank.

Zusammenfassung

Die Verwendung dieses Phenobarbital VET Control Kits dient der verlässlichen Erhebung der Qualität und Präzision des Phenobarbital VET Testkits (VT0211) und ermöglicht daher die Überwachung der Genauigkeit der Testergebnisse.

Benötigtes Material

(nicht im Kit enthalten)

- Pipetten

Vorbereitung und Handhabung

Die Kontrolle ist flüssig und fertig zur Verwendung. Den Fläschcheninhalt vor jeder Anwendung durch Umkehren des Fläschchens über mehrere Minuten gründlich mischen. Das Fläschchen öffnen, die erforderliche Kontrollsubstanzmenge in ein sauberes Probengefäß füllen. Probengefäß nach Abarbeitung der Kontrollmessungen entsorgen und neues Probengefäß bei weiteren Messungen verwenden um Kontamination der Kontrollflüssigkeit zu vermeiden. Die Kappe sofort wieder aufsetzen und das Fläschchen bei 2 – 8 °C aufbewahren. Immer Einweg-Pipettenspitzen verwenden!

Stabilität und Lagerung

Ungeöffnete Fläschchen sind bei 2 – 8 °C stabil bis zum am Label angegebenen Haltbarkeitsdatum. Geöffnetes Fläschchen ist bis zu 30 Tage stabil wenn es fest verschlossen bei 2 – 8 °C gelagert wird. Bakterielle Kontamination resultiert in einer Erhöhung der Trübung und/oder einem charakteristischen Geruch. Fläschchen verwerfen wenn Kontamination beobachtet wird.
NICHT EINFRIEREN!

Entsorgung

Bitte beachten Sie immer die lokalen gesetzlichen Vorschriften.

Warnungen und Vorsichtsmaßnahmen

Dieses Control Kit ist nur für den veterinären Einsatz!
NICHT VERSCHLÜCKEN! Beachten Sie die üblichen Laborvorschriften beim Umgang mit Reagenzien.



Spezies auf „*Kontrolle*“ stellen, bevor das Kontrollmaterial gemessen wird



Vergleichen Sie die Ergebnisse der Kontrollmessung mit den auf der lot-spezifischen Tabelle angeführten Grenzwerten



Befindet sich das Ergebnis außerhalb der Zielbereiche, wiederholen Sie die Messung. Ist das Ergebnis dann immer noch außerhalb der Zielbereiche, wenden Sie sich bitte an Ihren Distributor.